



NVS Technologies AG

Release Note October 20th, 2014 Firmware Revision 0408

- Bug fix in Fast Search Engine control which caused blocking of signal acquisition after a long time with no signals available.

*Note - all other FW 0408 functions and features are absolutely the same as for FW 0407.
Therefore no additional testing is needed on customer side for migration from FW 0407 to FW 0408.*

Compatibility

Firmware v.0408 is compatible with hardware revisions 4.x of the NV08C-CSM devices.